




**Figure 1. A schematic of robust diameter-controlled optical fiber drawing process**




**Figure 2. Another schematic of robust diameter-controlled optical fiber drawing process**




**Figure 3. A schematic of robust diameter-controlled optical fiber drawing process with one bare fiber diameter monitor**




**Figure 4. Another schematic of robust diameter-controlled optical fiber drawing process with one bare fiber diameter monitor considering shrinkage**




**Figure 5. Another schematic of robust diameter-controlled optical fiber drawing process with one bare fiber diameter monitor considering shrinkage at an adjustable position**



**Figure 6. A schematic of robust diameter-controlled optical fiber drawing process with only one bare fiber diameter monitor near the furnace**



**Figure 7. A schematic of robust diameter-controlled optical fiber drawing process with two bare fiber diameter monitors**



**Figure 8. Another schematic of robust diameter-controlled optical fiber drawing process with two bare fiber diameter monitors**






Figure 9. A schematic of diameter-measured optical fiber drawing process




Figure 10. A schematic of optical fiber drawing process (Pre Art 1)




Figure 11. Another schematic of optical fiber drawing process (Pre Art 2)